



August 29, 2021


The Philippine Stock Exchange, Inc.
6th Floor PSE Tower
28th corner 5th Avenue
Bonifacio Global City
Taguig City

Attention: **Ms. Janet A. Encarnacion**
Head, Disclosure Department

Gentlemen:

Attached please find a duly accomplished SEC Form 17-C. Thank you.

Very truly yours,


RACHEL R. HERNANDEZ
Corporate Secretary

SECURITIES AND EXCHANGE COMMISSION
SEC FORM 17-C

CURRENT REPORT UNDER SECTION 17
OF THE SECURITIES REGULATION CODE
AND SRC RULE 17.2(c) THEREUNDER

- 1.... **August 29, 2021**.....
Date of Report (Date of earliest event reported)
2. SEC Identification Number **A1998-18260** 3. BIR Tax Identification No. **202-464-633**
4.**FIRST GEN CORPORATION**.....
Exact name of issuer as specified in its charter
5.**Metro Manila, Philippines**..... 6. (SEC Use Only)
Province, country or other jurisdiction of Industry Classification Code:
incorporation
7. **6th Floor Rockwell Business Center Tower 3, Ortigas Avenue, Pasig City 1604**.....
Address of principal office Postal Code
8.**(632) 3449-6400**.....Issuer's telephone number, including area code
9. **N/A**Former name or former address, if changed since last report
10. Securities registered pursuant to Sections 8 and 12 of the SRC or Sections 4 and 8 of the RSA

Title of Each Class	Number of Shares of Common Stock Outstanding and Amount of Debt Outstanding (as of August 3, 2021)
Common Stock	3,596,575,505

11. Indicate the item numbers reported herein:**Item No. 9**

First Gen Corporation has been advised by its subsidiary, Prime Meridian PowerGen Corporation (PMPC), that the compressor of one of two gas turbines that comprise the approximately 97MW Avion power plant owned by PMPC is damaged. The Avion power plant features two units that utilize General Electric (GE) LM6000 PC dual fuel aero-derivative gas turbines/generators. According to GE, the LM6000 aero-derivative gas turbine, with over 1,300 units offering and 40 million operating hours, is a leader in the +40 MW space.

The damage to Avion Unit 2, which has a capacity of approximately 48.5 MW, was found during an ongoing routine inspection. After carefully reviewing the findings, GE has advised PMPC that Avion Unit 2 cannot be operated and will require further offsite assessment at a GE service depot abroad to determine the extent of the damage and effect repairs necessary to place the gas turbine back into service. PMPC has advised that Avion Unit 1 is not affected.

We will advise the Exchange of any material development in this regard.

SIGNATURE

Pursuant to the requirements of the Securities Regulation Code, the issuer has duly caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

FIRST GEN CORPORATION
Issuer

August 29, 2021
Date

By:


RACHEL R. HERNANDEZ
Corporate Secretary