



September 10, 2020

The Philippine Stock Exchange, Inc.
6th Floor PSE Tower
28th corner 5th Avenue
Bonifacio Global City
Taguig City

Attention: **Ms. Janet A. Encarnacion**
Head, Disclosure Department

Gentlemen:

Attached please find a duly-accomplished SEC Form 17-C pertaining to the company's 414MW San Gabriel Combined Cycle Power Plant. Thank you.

Very truly yours,


RACHEL R. HERNANDEZ
Corporate Secretary

SECURITIES AND EXCHANGE
COMMISSION SEC FORM 17-C

CURRENT REPORT UNDER
SECTION 17 OF THE SECURITIES
REGULATION CODE AND SRC RULE
17.2(c) THEREUNDER

- 1.... **September 10, 2020**.....
Date of Report (Date of earliest event reported)
2. SEC Identification Number **A1998-18260** 3. BIR Tax Identification No. **202-464-633**
4.**FIRST GEN CORPORATION**.....
Exact name of issuer as specified in its charter
- 5**Metro Manila, Philippines**..... (SEC Use Only)
Province, country or other jurisdiction of Industry Classification Code:
incorporation
7. **6th Floor Rockwell Business Center Tower 3, Ortigas Avenue, Pasig City 1604**.....
Address of principal office Postal Code
8.**(632) 3449-6400**..... Issuer's telephone number, including area code
9. **N/A** Former name or former address, if changed since last report
10. Securities registered pursuant to Sections 8 and 12 of the SRC or Sections 4 and 8 of the RSA

Title of Each Class	Number of Shares of Common Stock Outstanding and Amount of Debt Outstanding (as of August 31, 2020)
Common Stock	3,597,914,505

11. Indicate the item numbers reported herein:**Item No. 9**

Please be advised that Unit 70 of the company's 414MW San Gabriel Combined Cycle Power Plant tripped on September 5, 2020 due to activation of generator protection. As a result, Siemens Power Operations, Inc. (SPO) specialists prepared to conduct preliminary electrical tests on the generator within the following days to determine the nature of the problem and the cause of the trip, and reported in the evening of September 8, 2020 that those preliminary tests indicated an electrical fault in the generator. Further investigation and inspection of the generator is ongoing, and the plant has been declared unavailable for dispatch during this time. Pending completion of the experts' findings, the company is unable to provide an estimate of the expected return to service of the San Gabriel Plant.

We will inform the Exchange of any material development in this regard.

SIGNATURE

Pursuant to the requirements of the Securities Regulation Code, the issuer has duly caused this report to be signed on its behalf by the undersigned hereunto duly authorized.

FIRST GEN CORPORATION
Issuer

September 10, 2020
Date

By:

RACHEL R. HERNANDEZ
Corporate Secretary